

CERTIFICATE OF ELECTRONIC TRANSMITTAL UNDER 37 CFR 1.8

I hereby certify that this correspondence is being electronically transmitted  
to the Commissioner For Patents on the date set forth below,

Robyn K. Radde

(signature)

Date of signature and transmittal - September 2, 2010

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:	)	
Lawrence A. Parks et al.	)	Group Art Unit 3781
	)	
U.S. Patent No. 7,731,050	)	
Serial No. 10/555,047	)	
	)	Examiner: Robin Annette Hylton
Issued: June 8, 2010	)	
Filed: October 28, 2005	)	
	)	
For: CONTAINER AND CLOSURE	)	Attorney Docket 1-37296
COMBINATION INCLUDING	)	
SPREADING AND LIFTING CAMS	)	

---

September 2, 2010

Commissioner for Patents  
Office of Patent Publication  
ATTN: Certificate of Correction Branch  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 C.F.R. § 1.322

Honorable Sir:

Patentees and Assignee request the issuing of a Certificate of Correction for U.S. Patent No. 7,731,050 issued June 8, 2010, or alternatively, issuance of a corrected patent. It has been discovered that the paragraph including Col. 4, lines 39-49 of the patent include typographical errors that were not present in the original application or the published application. Furthermore, the typographical errors in Col. 4, lines 39-49 were not included in an Amendment filed January 11,


2010. The typographical errors are a result of an oversight on the part of the United States Patent and Trademark Office. Accordingly, please correct the paragraph including Col. 4, lines 39-49, as follows:

FIG. 4C shows the closure 40 having been rotated approximately ten (10.degree.) degrees relative to the fully closed position as illustrated in FIG. 4A and an additional five (5.degree.) degrees of rotation therein illustrated in FIG. 4B. The locking tab 46 of the closure 10 is in full slidable contact with the spreading [[earn]] cam 28 of the closure 10 causing maximum flexing of the skirt 44 away from the outer surface of the finish 16 of the container 10, and the lower surface of the locking tab 46 has been caused to be ~~earomed~~ cammed upwardly by the lifting cam 30 to further lift the closure 40 in respect of the container 10. The closure 40 is still secured to the container 10.

Issuance of the Certificate of Correction or the corrected patent is requested to correct the typographical errors identified herein above.

Since the errors for which a Certificate of Correction is sought are a result of an oversight on the part of the United States Patent and Trademark Office, no fee is due (35 U.S.C. § 254).

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Donald R. Fraser", written over a horizontal line.

Donald R. Fraser

Reg. No. 17,919

Attorney for Patentees and Assignee

Fraser Clemens Martin & Miller LLC  
28366 Kensington Lane  
Perrysburg, Ohio 43551  
(419) 874-1100